104 Calle De La Cruz Marker San Juan
Puerto Rico

PR 7 - SATU

PHOTOGRAPHS

REDUCED COPIES OF MEASURED DRAWINGS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
NATIONAL PARK SERVICE
U.S. DEPARTMENT OF THE INTERIOR
WASHINGTON, D.C. 20240

Form 10-920 (June 1983)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

2574H 1274 1262-4 181

ARCHITECTURAL DATA FORM

	COUNTRY		
STATE	COUNTY TOWN OR VICINITY		ΓY
Puerto Rico	Puerto Rico San J		· · · · · · · · · · · · · · · · · · ·
HISTORIC NAME OF STRUCTURE (INCL	UDE SOURCE FOR NAME)		HABS NO.
104 Calle De La Cru	z (House)	<u>-</u>	PR-64
SECONDARY OR COMMON NAMES OF STRUCTURE			
none (but originally 20 Calle De La Cruz)			
COMPLETE AOORESS (DESCRIBE LOCATION FOR RURAL SITES)			
same as historic name			
DATE OF CANSTRUCTION (INCLUDE SOURCE) ARCHITECT(S) (INCLUDE SOURCE)			
precise A not known (18th co	entury) not known		
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)			
Excellent example of a fine town house of 18th century San Juan. Typical of this building type , businesses occupy spaces at ground level near the street with families living in spaces beyond and on other levels.			
STYLE (IF APPROPRIATE) not applicable			
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Bearing wall masonry of brick, stone and earth with stucco finish. The structural system is wall bearing and beam system			
SHAPE AND DIMENSIONS OF STRUCTUS	RE (SKETCHED FLOOR PLANS ON SEPA)	RATE PAGES ARE A	ACCEPTABLE)
EXTERIOR FEATURES OF NOTE Most notable exterior features are two fine balconies supported by cantilevered wood beams, cast iron columns support the balcony roof of wood frame and corrugated sheet metal. The balustrade is cast iron.			
INTERIOR FEATURES OF NOTE (DESCR	IBE FLOOR PLANS, IF NOT SKETCHED)		
The stairway is exceptionally fine, with marble treads and wood or concrete nosing and fragments of tile risers.			
MAJOR ALTERATIONS AND AODITIONS beyond the addition	S WITH DATES of electic lighting not known		
PRESENT CONDITION AND USE			
good appearance. Two small businesses at ground level near the street and tenants above.			
OTHER INFORMATION AS APPROPRIAT	E		
		·	
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)			
Above based on report prepared	d by F. Blair Reeves, HABS, San	Juan,1966	
COMPILER, AFFILIATION Bill Le	oovich, HABS/HAER	0A ⁻ 2/	TE /5/8 6